

Fusion 360 Files won't Open in TM CAD

Symptoms:

Torchmate CAD will not display imported .dxf file created in Fusion 360.

Verification:

- After attempting to import the .dxf file created in Fusion 360, the CAD screen does not show the part created.
- The screen will "blink" and zoom into the material space.

Cause:

One of the existing Torchmate CAD files needs to be updated to translate the .dxf files produced from Fusion 360.

Solution:

- 1. Download the impdxf.zip folder from here
- 2. Extract the downloaded folder.
- 3. Copy the impdxf.dll file.
- 4. Paste the file onto the Torchmate CAD folder on the C: drive
- 5. Select the option to overwrite the existing file.

Fusion 360 Files won't Open in TM CAD

DOC #:7239-0-US70-080818-DS-01-02

Rev#:00

Rev Date:8/9/2018



